

KENTUCKY HISTORIC RESOURCES
INDIVIDUAL SURVEY FORM
(KHC 91-1)

COUNTY Lewis
RESOURCE# Lw-20
RELATED GROUP #
INTENSIVE DOC. /
EVALUATION S /
DESTROYED /

For instructions, see the Kentucky Historic Resources Survey Manual.

1. NAME OF RESOURCE (how determined): <u>1 / Purcell - McGlone House</u>	16. PLAN:										
2. ADDRESS/LOCATION: <u>South side of Engle Rd. approx. 1 mile west of Crooked Creek Rd. intersection</u>	E / <u>Hall - Parlor</u> first <u>/</u> second <u>/</u> third										
3. UTM REFERENCE: Quad. Name: <u>Manchester Islands, Ky - Ohio</u> Date: <u>1961</u> Zone: Easting: <u>2 / 7 / 8 / 3 / 8 / 0 /</u> Northing: <u>4 / a / 8 / 3 / 8 / 6 / 0 /</u> Accuracy: <u>A /</u>	17. STYLISTIC INFLUENCE: <u>6 / Craftsman; /</u> first <u>/</u> ; <u>/</u> second <u>/</u> ; <u>/</u> third										
4. OWNER/ADDRESS: <u>Mead Realty Group</u>	18. STYLE DEVELOPMENT: <u>/</u> first <u>/</u> second <u>/</u> third										
5. FIELD RECORDER/AFFILIATION: <u>Karen Hudson / PCRA</u>	19. FOUNDATION: <table border="0"><thead><tr><th>TYPE</th><th>MATERIAL</th></tr></thead><tbody><tr><td><u>/</u></td><td><u>/</u> original</td></tr><tr><td><u>/</u></td><td><u>/</u> replacement</td></tr></tbody></table>	TYPE	MATERIAL	<u>/</u>	<u>/</u> original	<u>/</u>	<u>/</u> replacement				
TYPE	MATERIAL										
<u>/</u>	<u>/</u> original										
<u>/</u>	<u>/</u> replacement										
6. DATE RECORDED: <u>July 1992</u>	20. PRIMARY WALL MATERIAL: <u>I / Weatherboard</u> original <u>/</u> replacement										
7. SPONSOR: <u>Mead Realty Group</u>	21. ROOF CONFIGURATION/COVERING: <table border="0"><thead><tr><th>CONFIGURATION</th><th>COVERING</th></tr></thead><tbody><tr><td><u>A / gable, side</u></td><td><u>/</u> original</td></tr><tr><td><u>/</u></td><td><u>/</u> replacement</td></tr></tbody></table>	CONFIGURATION	COVERING	<u>A / gable, side</u>	<u>/</u> original	<u>/</u>	<u>/</u> replacement				
CONFIGURATION	COVERING										
<u>A / gable, side</u>	<u>/</u> original										
<u>/</u>	<u>/</u> replacement										
8. INITIATION: <u>3 /</u>	22. CONDITION: <u>G / good</u>										
9. OTHER DOCUMENTATION/RECOGNITION: <table border="0"><tr><td><u>Survey</u></td><td><u>HABS/HAER</u></td></tr><tr><td><u>KY Land</u></td><td><u>Local Land</u></td></tr><tr><td><u>NR</u></td><td><u>R&C</u></td></tr><tr><td><u>NHL</u></td><td></td></tr><tr><td>Other:</td><td></td></tr></table>	<u>Survey</u>	<u>HABS/HAER</u>	<u>KY Land</u>	<u>Local Land</u>	<u>NR</u>	<u>R&C</u>	<u>NHL</u>		Other:		23. MODIFICATION: <u>3 / Major</u>
<u>Survey</u>	<u>HABS/HAER</u>										
<u>KY Land</u>	<u>Local Land</u>										
<u>NR</u>	<u>R&C</u>										
<u>NHL</u>											
Other:											
10. ORIGINAL PRIMARY FUNCTION: <u>0 / 1 / A / dwelling</u>	24. NEGATIVE FILE #: <u>92/02/ 2-9</u> Write resource # on back of all prints.										
11. CURRENT PRIMARY FUNCTION: <u>9 / 9 / v / Valant</u>											
12. CONSTRUCTION DATE: <u>6 / c. 1850</u> estimated <u>/ / / / /</u> documented											
13. DATE OF MAJOR MODIFICATIONS (specify): <u>3 / chimney, porch, windows, dormer, rear additions</u> <u>/ interior alterations - mantel, woodwork</u>											
14. CONSTRUCTION METHOD/MATERIAL: <u>L / 3 / Log / Half Dovetail</u> original <u>/ / /</u> subsequent											
15. DIMENSIONS: Height <u>1.5</u> Width <u>3</u> Depth <u>1</u>											




Figure 10. Plan of the Purcell-McGlone House (LW-20)



Plate 18. Purcell-McGlone House (LW-20)

Brice Virgin purchased land from John Stevenson in 1848 (Lewis County Deed Book K, page 268). His son, Mott Virgin, obtained ownership of the farm in 1907 (Lewis County Deed Book 28, page 90). In 1945, the farm, which was referred to as the "Brice Virgin Home Farm," was sold.

RECOMMENDATION: The form (dimension and stairway room) and construction method (post in the ground) of the Mott Virgin home are unusual. The pegged, timber frame barn appears to be of an earlier construction. Additional research is needed to determine the significance of the site.

SURVEY NUMBER: LW-21.1
FUNCTION: Dwelling
FORM: I-house
CONSTRUCTION: Frame
DIMENSIONS: 15'x15'
YEAR BUILT: ca. 1910
EVALUATION: Potentially eligible member of a group

DESCRIPTION: This balloon frame, two-story home was constructed by Mott Virgin around 1910 (Figure 11; Plates 19 and 20). It is a central-hall I-house with the stairs to the second floor located in an enclosed room on the front wall. The house has unusually small dimensions. Each room is approximately fifteen feet square, and the hallway is only about four feet wide. The room to the north has a post in the ground foundation. The south side room has a rough poured concrete foundation. The entire home has diagonal sheathing below weatherboard. The structure has three brick chimneys. One is located on the interior end of both of the main rooms, and one is located on the end of the stairway room. The interior is plastered. The building is in poor condition.